

M300 1969-71 (Front 12.12" x 2"; Rear 13" x 2.5")

	Master Cylinder		Vacuum Booster	Wheel Cylinder	
	Repair Kit	Rebuilt	Rebuilt	Front	Rear
Bore	1 1/4" (1.25")			1 1/8" (1.125")	1 1/4" (1.25")
Chrysler P/N	3004916 (thru S/N 1S351952) 	2953380 (thru S/N 1S351952) 	2825621 (thru S/N 1S351952) 	1793119 (left) 1793118 (Right) 	The 13" x 2.5" drum size is not supported in the Dodge MH Parts Manual 
Bendix	22924			33087 (Left) 33088 (Right)	33073 (Left) 33074 (Right)
AC-DELCO				172-549 (Left) 172-550 (Right) 18E24 (Left) 18E25 (Right)	172-338 (Left) 172-339 (Right) 172-726 (Left) 172-727 (Right)
AMERICAN REMANUFACTURING				84-46004 (Left) 84-46003 (Right)	84-38007 (Left) 84-38008 (Right)
AUTO-SPECIALTY				W-88004 (Left) W-88003 (Right) W-93010 (Left) W-93009 (Right)	W-84007 (Left) W-84008 (Right)
CARQUEST				EW24955 (Left) EW24954 (Right)	EW9344 (Left) EW9345 (Right)
CASTING				18292 (Left) 18293 (Right) 302889L (Left) 303889R (Right) 304930L (Left) 304931R (Right) 5453821 (Left) 5453822 (Right) AD2190A (Left) AD2191A (Right) FD18292 (Left) FD18293 (Right)	583 (Left) 585 (Right) 617432 (Left) 617438 (Right)
CENTRIC				134.68004 (Left) 134.68003 (Right)	134.64007 (Left) 134.64008 (Right)
CERTIFIED				W24955 (Left) W24954 (Right)	W9344 (Left) W9345 (Right)
GM					2622919 (Left) 2622920 (Right) 3767122 (Left) 3767121 (Right)
NAPA	UP 214	TS 101643	NBB 519241	UP24954 (Left) UP24955 (Right)	UP9344 (Left) UP9345 (Right)
RAYBESTOS				WC-24955 (Left) WC-24954 (Right)	WC-9344 (Left) WC-9345 (Right)
WAGNER				F24955 (Left) F24954 (Right)	F9344 (Left) F9345 (Right)





M300 1972-73 (12" x 3" Drums Front and Rear)

	Master Cylinder		Vacuum Booster	Wheel Cylinder	
	Rebuilt	New	Rebuilt	Front	Rear
Bore	1 1/8" (1.125")			1 1/8" (1.125")	1 1/16" (1.06")
Chrysler P/N	3004914: 1972 M300 (after S/N 1S351952) 3549078: 1973 R300	3549832: 1972 M300 (after S/N 1S351952) 3491500: 1973 R300	3633549: 1972 M300 (after S/N 1S351952) 3732195: 1973 R300	1793119 (left) 1793148 (Right)	3633321 (left) 3633322 (Right)

					
Bendix	R11405	11405		33087 (Left) 33088 (Right)	33461 (Left) 33462 (Right)
A-1	10-1405				
AC-DELCO		174-312 174-313 18M15		172-549 (Left) 172-550 (Right) 18E24 (Left) 18E25 (Right)	172-406 (Left) 172-407 (Right)
AMERICAN REMANU- FACTURING		83-40001		84-46004 (Left) 84-46003 (Right)	84-46011 (Left) 84-46012 (Right)
AUTO- SPECIALTY		M-87001 M-87019		W-88004 (Left) W-88003 (Right) W-93010 (Left) W-93009 (Right)	W-88011 (Left) W-88012 (Right)
CARQUEST		E71259		EW24955 (Left) EW24954 (Right)	EW44491 (Left) EW44490 (Right)
CASTING		121 2225647 2225771 29910C FF85573 FF99145		18292 (Left) 18293 (Right) 302889L (Left) 303889R (Right) 304930L (Left) 304931R (Right) 5453821 (Left) 5453822 (Right) AD2190A (Left) AD2191A (Right) FD18292 (Left) FD18293 (Right)	29366C (Left) 29365C (Right) 29413C (Left) 29412C (Right) 616189L (Left) 616190R (Right) 616248 (Left) 616249 (Right) 651 (Left) 650 (Right) FD41766 (Left) FD41767 (Right)
CENTRIC		130.67001		134.68004 (Left) 134.68003 (Right)	134.68011 (Left) 134.68012 (Right)
CERTIFIED				W24955 (Left) W24954 (Right)	W41718 (Left) W41719 (Right) W9090 (Left) W9091 (Right)
FRICION MASTER	1405				
GM					
NAPA	TS 101405 (M300) TS 101339 (R300)	SS 4736258 (M300) UP 36258 (M300) SS 4736461 (R300) UP 36461 (R300) UP 525 (M300 Kit)	NBB 5473143 (R300) NBB 509261 (R300 W/Master Cyl)	UP 24954 (Left) UP 24955 (Right)	UP 37219 (Left) UP 37218 (Right) UP 37083 (Left) UP 37084 (Right)
POWER UNIT EXCHANGE	66786, 71259				
PRECISION REBUILDERS			2514023 (M300)		
PRIOR	1331R, 1373R				
RAYBESTOS	RMC-36258	MC-36258		WC-24955 (Left) WC-24954 (Right)	WC-37083 (Left) WC-37084 (Right)
TRU-TORQUE		M71259			
WAGNER	R71259	F71259		F24955 (Left) F24954 (Right)	F41718 (Left) F41719 (Right)



M300/RM300 1973-78 (Front 12.82" Disc; 12" x 3" Rear Drum)

	Master Cylinder			Vacuum Booster	Front
	Repair Kit	New	Rebuilt	Rebuilt	Caliper (12.82" Disc)
Bore		1 1/8" (1.125")			3.0"
Chrysler P/N	3838022	3821715 4089212 B11494	BR11494	3732195	74-75 3633115 (Left) 3633114 (Right) 76-Up 4032825 (Left) 4032824 (Right) 4026122 (Rebuild Kit)




					
Bendix	22705	11494	R11494	2510728	L55117M (Left; W/Pads-Hdw; New) R55117 (Left; Remfd) SL55117 (Left; W/Hdw; New) L55116M (Right; W/Pads-Hdw; New) R55116 (Right; Remfd) SL55116 (Right; W/Hdw; New) 66817 (Kit) 90018S (Piston)
A-1			10-1339, 10-1511		16-4074 16-4074S
AC-DELCO		174-246 174-260 174-263 174-288 174-297 174-391 174-429 18M13,18M19 18M48,18M72			18R586
AMERICAN REMANU- FACTURING		83-36105 83-38001 83-40002			10-4074
AUTO- SPECIALTY		M-82105 M-84001 M-84001E M-87002			40-87006
CARQUEST		E71285 E77008			RL6074 RL7173
CASTING		123, 1530 2225871, 2225871A 2226311,2229771 2951, 29881 29881C, 29906C 29932C, 44A, 45465 5460346, 5468114 5468115, 5470409 5470410, 5472003 616588, FD2951 FF84785, FF99138			
CENTRIC		130.62105 130.64001 130.67002			141.67006
CERTIFIED		M80568 M86488	RM80568		
CHAMPION REBUILDERS			27-1494, 27-1517		
CONI-SEAL		MC250040			
FRICION MASTER			1339, 1511		
GM		406389 5470665			
NAPA	UP 712 (OEM Cyl Kit) UP 663 (Aftermkt Cyl Kit)	SS 4736461 UP 36461	TS 101576	NBB 5473143 NBB 509261 (W/Master Cyl)	<u>Left</u> SDC 2423014 (W/Hdw; Remfd) UP 4423014 (W/Pads-Hdw; Remfd) TS 1423014 (W/Pads-Hdw; Remfd) <u>Right</u> SD C2423015 (W/Hdw; Remfd) UP 4423015 (W/Pads-Hdw; Remfd) TS 1423015 (W/Pads-Hdw; Remfd) UP 638 (Seal Kit) UP 85020S (Steel Piston) UP 82115A (Hdwr Kit)

POWER UNIT EXCHANGE			71256, 71285 77008		
PRECISION REBUILDERS				2510965	
PRIOR			1381R, 1477R 1494R		
RAYBESTOS		MC-36280, MC-36364 MC-36461	RMC-36280 RMC-36461		RC4074
TRU-TORQUE		M71285, M73342 M80568, M89160			
WAGNER		F73342, F79820 F80568, F86488 F99298	R73342, R79820 R80568		L83262



M-375 1969-71 (Front 14.12" x 2"; Rear 14.12" x 3")


	Master Cylinder		Vacuum Booster	Wheel Cylinder	
	Repair Kit	New	Rebuilt	Front	Rear
Bore	1 1/4" (1.25")			1 1/2" (1.5")	1 3/8" (1.375")
Chrysler P/N	1881981 (thru S/N 1S352788) 	2914462 (thru S/N 1S352788)	2230707 (thru S/N 1S352788)	The 14.12" x 2" drum size is not in supported in the Dodge MH Parts Manual	3633311 (Left) 3633312 (Right) 
NAPA	UP 214	UP 27304			UP 37669 (Left) UP 37670 (Right)
PRECISION REBUILDERS			2512062		

M-375 1972-73 (Front 14.2" x 2.5"; Rear 14.12" x 3")

	Master Cylinder		Vacuum Booster	Wheel Cylinder	
	Rebuilt	New	Rebuilt	Front	Rear
Bore	1 1/8" (1.125")			1 1/16" (1.063")	1 3/8" (1.375")
Chrysler P/N	3632678 (after S/N 1S352788) 	3491977 (after S/N 1S352788) 	3632883 (after S/N 1S352788)	2908647 (left) 2908646 (Right)	3633311 (Left) 3633312 (Right) 
NAPA	UP 792			UP 13368 (left) UP 13369 (Right)	UP 37669 (Left) UP 37670 (Right)




M-400 1975-Up RM-350 1973-74

	Master Cylinder			Vacuum Booster	Hydro Boost
	Repair Kit	New	Rebuilt	(1973-75) Rebuilt	(1976-Up) Repair Kit
Bore/Piston Dia.	1 1/4" (1.25")				
Chrysler P/N	3744948 (1973-75) 4049657 (1976-Up)	3640282 (1973) 3820823 (1974-75) 4031345 (1976-Up) 		3640050 (1973 RM-350) (Mounted to MC) 4030334 (74-75) (Mounted to Frame)	4031352 (Assembly)  Repair Kits 4049664: Charging Valve 4049665: Seal 4049666: Cover Seal 4049667: Check Valve (Refer to Parts manual for descriptions)

Bendix	22575 22924	11133 (R-350) 11583 (76-Up)	R11583 (76-Up)		
NAPA	 <p>UP 792 UP 214</p>	UP 27304 (73 R-350) UP 39013 (74-75) UP 39012 (76-Up) TS 101583 (76-Up)		MBI RV2512063X (74-75)	NBB 529393 (Assy)
PRECISION REBUILDERS				2510965 (73) 2512063 (74-75)	2771173 (76-77 Assy) 2770726 (78 Assy)
A-1					
AC-DELCO		18M8 (R-350) 174-554 (76-Up) 18M68 (76-Up)			
AMERICAN REMANUFACTURING		83-48001 (R-350) 83-46001 (76-Up)			
AUTO-SPECIALTY		M-91001 (R-350) M-88001 (76-Up)			
CARQUEST		E27304 (R-350) E84058 (76-Up)			
CASTING					
CENTRIC		130.81001 (R-350) 130.68001 (76-Up)			
CERTIFIED		M27304 (R-350)			
POWER UNIT EXCHANGE		27304 (R-350)			
RAYBESTOS		MC-27304 (R-350) MC-39012 (76-Up)			
WAGNER		F27304 (R-350) F84058 (76-Up)			

**M-500 1975-Up
RM-400 1973-74**

	Master Cylinder		Vacuum Booster	Hydro Boost
			(1973-75)	(1976-Up)
	Repair Kit	New	Rebuilt	Repair Kit

Bore/Piston Dia.	1 1/4" (1.25")				
Chrysler P/N	3744948 (1973-75) 4049657 (1976-Up)	3540282 (1973) 3820823 (1974-75) 4031345 (1976-Up) 		3640050 (1973 RM-400) (Mounted to MC) 4030334 (74-75) (Mounted to Frame)	4031352 (Assembly)  <u>Repair Kits</u> 4049664: Charging Valve 4049665: Seal 4049666: Cover Seal 4049667: Check Valve (Refer to Parts manual for descriptions)
Bendix	22575 22924	11133 (R-400) 11583 (76-Up)	R11583 (76-Up)		
NAPA		UP 27304 (73 R-350) UP 39013 (74-75) UP 39012 (76-Up) TS 101583 (76-Up)		MBI RV2512063X (74-75)	NBB 529393 (Assy)
PRECISION REBUILDERS				2503151 (73) 2512063 (74-75)	2771173 (76-77 Assy) 2770726 (78 Assy)
A-1					
AC-DELCO		18M8 (R-400) 174-554 (76-Up) 18M68 (76-Up)			
AMERICAN REMANUFACTURING		83-48001 (R-400) 83-46001 (76-Up)			
AUTO-SPECIALTY		M-91001 (R-400) M-88001 (76-Up)			
CARQUEST		E27304 (R-400) E84058 (76-Up)			
CASTING					
CENTRIC		130.81001 (R-400) 130.68001 (76-Up)			
CERTIFIED		M27304 (R-400)			
POWER UNIT EXCHANGE		27304 (R-400)			
RAYBESTOS		MC-27304 (R-400) MC-39012 (76-Up)			
WAGNER		F27304 (R-400) F84058 (76-Up)			

[1]
Dave Bailey:

[2]
Dave Bailey: